Rose Garden

Activities / Amenities

□ Gardens	Bathroom Building
□ Parking	

Gardens

Route

The typical route throughout the gardens is a 6'-6" wide paver path. A route is provided to the border of each of the defined garden areas.

JQP, Inc. Recommends

Priority 3- Ensure the route is maintained to prevent any changes in level exceeding 1/2" between pavers. *ADA* 303



Route

The paver route does not currently extend into the center of the northeast garden (with benches in the center).

JQP, Inc. Recommends

Priority 3- Add an accessible link to the center of the northeast garden. *ADA 206.2.2*



Dog Bags

There is currently a big dispenser provided for the collection of dog droppings. The dispenser is currently located approximately 3' from the accessible route.

JQP, Inc. Recommends

Priority 3- Add an accessible route to the dog bags or relocate to an accessible location. ADA 206.2.2



Bathroom Building



Bathroom Building

A bathroom building is provided near the parking lot. JQP, Inc. prepared a detailed report of the bathroom building, it has been included in the facilities report.

Parking

Quantity

There is room for 57 vehicles in the parking, including 2 spaces designated as accessible. Based on the total number of parking spaces, a minimum of 3 accessible parking spaces are required.

JQP, Inc. Recommends

Priority 2- Designate 1 additional accessible parking space. *ADA 208.2*

Location

The designated accessible parking spaces are not currently located on the shortest accessible route to the bathroom building or the park entrance.

JQP, Inc. Recommends

Priority 2- Relocate the accessible parking spaces to behind the bathroom building.

Parking

The designated accessible spaces are currently 12' wide and do not provide an aisle.

The signs designating the accessible parking spaces are currently at 84" AFF.

JQP, Inc. Recommends

Priority 2- When relocating the accessible parking spaces stripe to provide an 8' wide minimum space with an 8' wide minimum aisle. (Note: 2 spaces can share an aisle.) MN1341 502.4.2

Priority 3- Lower the parking signs so the bottom edge is 60"-66" above the surface of the parking space. *MN1341 502.7*

