# Washington Square

### Activities / Amenities

- □ Play Equipment

Picnic

- □ Parking

# **Play Equipment**

## **Defined Play Area**

The defined play area includes 1 composite play structure, to-fro swings (2 strap style, 2 bucket style), digger, talk tube and play panels. An adequate quantity of ground level components have been provided. This is a good example of accessibility.

Loose fill sand is used throughout the defined play area.

## JQP, Inc. Recommends

Priority 2- Replace the loose fill sand with a surface material with a type that complies with ASTM 1292 for impact attenuation and ASTM 1951 for accessibility. ADA 206.2.17







#### **Defined Play Area- Route**

There is not currently an accessible route to the defined play area.

## JQP, Inc. Recommends

*Priority 1-* Create an accessible route to the defined play area. *ADA 206.2.2* 



#### Picnic



## Picnic Tables- Northwest

There are 4 tables in the grass near the play equipment. Currently none of the tables provides a position with knee and toe clearance and there is not an accessible route.

#### JQP, Inc. Recommends

**Priority 2-** Create an accessible route to the picnic area.

**Priority 3-** Provide a picnic table that provides knee and toe clearance. Recommended based on Draft Accessibility Guidelines for Outdoor Developed Areas 1011.4

#### Bench

#### Bench

There are 4 benches located in the sand within the defined play area.

#### JQP, Inc. Recommends

**Priority 3-** Create an accessible route and clear ground space adjacent to the short end of the bench. *ADA* 903.2



## **Dog Bags**



#### Dog Bags

There is currently a big dispenser provided for the collection of dog droppings. The dispenser is currently located in the grass near the picnic tables. **JQP, Inc. Recommends** 

**Priority 3-** Add an accessible route to the dog bags or relocate to an accessible location. ADA 206.2.2

#### Parking

#### Parking

There is a bump-out along Regent Street with room for approximately 10 vehicles parked parallel or 30 vehicles parked diagonal. (There is not striping.) There is not currently any designated accessible parking.

## JQP, Inc. Recommends

**Priority 2-** Designate 1 accessible parking space. ADA 208.2

**Priority 2-** Stripe the accessible parking spaces to provide an 8' wide minimum space with an 8' wide minimum aisle. *MN1341 502.4.2* 

