

FOR IMMEDIATE RELEASE



City of Duluth Communications Office

Mayor Emily Larson
411 West First Street • Duluth, Minnesota 55802 • www.duluthmn.gov

*For more information contact Kate Van Daele,
Public Information Officer at 218-730-5309*

DATE: 2/22/2021

SUBJECT: Crews on scene at a water main break in the Kenwood neighborhood

BY: Kate Van Daele, Public Information Officer

Crews on scene at a water main break in the Kenwood neighborhood

[Duluth, MN] City of Duluth Utility Operations crews are responding to a broken water main located in the Kenwood neighborhood. The break was reported at 2:16 p.m. and is located at 116 West Cleveland Street. Water has been shut off on West Cleveland Street from Kenwood Avenue to the dead end on Cleveland Street. It is not known at this time how long it will take to fix the break.

Crews ask drivers to be conscious of their work and avoid the work zone if possible.

City staff would like to thank those in the affected area for their patience. Crews are working to repair the break and restore water service as quickly as they can.

To see current utility outages, please view the Outage Map by clicking here:

<https://duluthmn.maps.arcgis.com/apps/Viewer/index.html?appid=7a03e4fdeb13451c89f4388105946a35>.

A Northland Alert has been sent to those in the affected area. To subscribe for Northland Alert, please visit

<https://duluthmn.gov/northlandalert/>.

###