


Partial Copy JTD Tank - Tank
From MPCA LEAK file 2094 Excavation Rpt. Ref. 5c
Former Food Services of America 1990

ADDITIONAL COMMENTS, DETAILS AND DESCRIPTIONS: The tank itself appeared to be in pretty good shape, all contaminated soil was removed to the best of the ability without destroying the standing structures. Because of high water table they were going to skim product off top of the water, then sponge off the rest before filling in with clean sand

Sketch the property site and tank location(s) in the space provided below.



Please fill out this form as completely as possible. Provide a copy to the local Fire Department Official and send the original form to the MPCA at the address below.

Minnesota Pollution control Agency
Tanks and Spills Section
Hazardous Waste Division
520 Lafayette Road, St. Paul, Minnesota 55155